

FIG. 1




FIG. 2









FIG. 3










FIG. 7

DOT 190° 544E960




FIG. 8



1	0	1	0	1	0	1	0	1	0	1
0	1	0	1	0	1	0	1	0	1	0
1	0	1	0	1	0	1	0	1	0	1

FIG. 9

0	3	6	9	12	15	18	21	24
1	4	7	10	13	16	19	22	25
2	5	8	11	14	17	20	23	26

FIG. 11

0	0	0	0	0	0	0	0	0
0	1	0	1	0	1	0	1	0
1	1	1	1	1	1	1	1	1

FIG. 13

0	1	0	1	0	1	0	1	0
1	0	1	0	1	0	1	0	1
0	1	0	1	0	1	0	1	0

FIG. 10

000	0 $\frac{1}{2}$ 0	010	$\frac{1}{2}$ 00	$\frac{1}{2}$ $\frac{1}{2}$ 0	$\frac{1}{2}$ 10	100	1 $\frac{1}{2}$ 0	110
00 $\frac{1}{2}$	0 $\frac{1}{2}$ $\frac{1}{2}$	01 $\frac{1}{2}$	0 $\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$	$\frac{1}{2}$ $\frac{1}{2}$ $\frac{1}{2}$	$\frac{1}{2}$ 1 $\frac{1}{2}$	10 $\frac{1}{2}$	1 $\frac{1}{2}$ $\frac{1}{2}$	11 $\frac{1}{2}$
001	0 $\frac{1}{2}$ 1	011	$\frac{1}{2}$ 01	$\frac{1}{2}$ $\frac{1}{2}$ 1	$\frac{1}{2}$ 11	101	1 $\frac{1}{2}$ 1	111

FIG. 12

0	0	0	0	0	0	0	0	0
1	0	1	0	1	0	1	0	1
1	1	1	1	1	1	1	1	1

FIG. 14

0	0	1	0	1	1	0	0	1
0	1	1	0	0	1	0	1	1
0	0	1	0	1	1	0	0	1

FIG. 15

0	1	1	0	0	1	0	1	1
0	0	1	0	1	1	0	0	1
0	1	1	0	0	1	0	1	1

FIG. 16


0	0	0	1	0	1	1	1	1
0	0	0	1	0	1	1	1	1
0	0	0	0	1	0	1	1	1

FIG. 17

0	0	0	1	0	1	1	1	1
0	0	0	0	1	0	1	1	1
0	0	0	1	0	1	1	1	1

FIG. 18

00150 442500



1902

FIG. 19

FIG. 20